

SECRET

ROUTING

INFO : OSA 1-15

TOR: 0259Z 18 DEC 63

ROUTINE

OXCART

IN 54968

好FO

CITE CABLE 3113

OXCART MEDICAL

FOLLOWING COMMENTS CONCERN SUIT FLIGHT OF [REDACTED] IN
ARTICLE 127, 17 DEC 63. TIME OF FLIGHT 1:10, TIME IN SUIT
3:40. PILOT PREBREATHED ONE HOUR. PILOT EXPERIENCED HOT SPOT
ON LEFT TEMPLE CAUSED FROM HELMET REGULATOR. PILOT HAD
DIFFICULTY GRASPING NEW "D" RING WITH SUIT PRESSURIZED.

END OF MESSAGE

DOCUMENT NO. _____
NO CHANGE IN CLASS. *X*
☐ DECLASSIFIED
CLASS. CHANGED TO: TS S C *2011*
NEXT REVIEW DATE: _____
AUTH: HR 70-2
DATE: *16/9/81* REVIEWER: *064540*

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy No.